

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/25/2012	3. Time Prepared 1300
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Chicago, IL
8. Activity Log			
Time	Major Events		
08:00	<ul style="list-style-type: none"> Arrive at ICP 		
0810	<ul style="list-style-type: none"> Arrived C0.4 boat launch, no ice or sheen observed. MP5.63 RDB observed a very thin layer of ice forming. Ceresco Dam control point boom no sheen or ice observed. MP5.70 RDB observed sheen and tar globs within the vegetation. Ceresco Dam control point, no ice observed forming along the boom. Ceresco Dam impoundment no ice observed forming along the LDB. Ceresco Dam control point boom observed sheen collecting along the boom. MP5.5 LDB observed no ice forming along the river bank. MP5.63 LDB above the railroad trestles observed a very thin layer of ice forming. MP5.63 LDB no ice observed, sheen was observed. MP5.63 LDB no ice observed, sheen was observed. 		
10:00	<ul style="list-style-type: none"> Arrive at the South Mill Pond. MP15.5 South Mill Pond observed ice forming. MP15.5 South Mill Pond observed sheen and tar globs within the ice. MP21.5 Custer Bridge no ice or sheen observed. 		
11:00	<ul style="list-style-type: none"> Arrived at Morrow Lake E4 boat launch. Morrow Lake Delta no ice observed forming within the neck of the delta. Morrow Lake Delta observed the anchor poles and boom in place. . 		
11:30	Return to ICP. Prepare photo log and 214.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			